

CERTIFICATE OF COMPLIANCE

Certificate Number 20181012-E194432
Report Reference E194432-20181012
Issue Date 2018-OCTOBER-12

Issued to: BUD INDUSTRIES
4605 E 355TH ST
WILLOUGHBY, OH 44094 USA

This is to certify that representative samples of INDUSTRIAL CONTROL PANELS
See Addendum Pages for Models


Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 508A, Industrial Control Panels;
CSA-C22.2 No. 14, Industrial Control Equipment

Additional Information: See the UL Online Certifications Directory at www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product., ,



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>




CERTIFICATE OF COMPLIANCE

Certificate Number 20181012-E194432
Report Reference E194432-20181012
Issue Date 2018-OCTOBER-12

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Industrial control panel enclosures: Models NBA-10140, NBA-10141, NBA-10142, NBA-10143, NBA-10144, NBA-10145, NBA-10148, NBA-10149, NBA-10152, NBA-10153, NBA-10156, NBA-10178, , NBA-10160, NBA-10161, NBA-10162, NBA-10163, NBA-10164, NBA-10165, NBA-10168, NBA-10169, NBA-10172, NBA-10173, NBA-10176, , NBA-15140, NBA-15141, NBA-15142, NBA-15143, NBA-15144, NBA-15145, NBA-15148, NBA-15149, NBA-15152, NBA-15153, NBA-15156, NBC-15372, , NBA-15160, NBA-15161, NBA-15162, NBA-15163, NBA-15164, NBA-15165, NBA-15168, NBA-15169, NBA-15172, NBA-15173, NBA-15176, NBB-10220, NBB-10221, NBB-10222, NBB-10223, NBB-10240, NBB-10224, NBB-10225, NBB-10226, NBB-10241, NBB-10227, NBB-10243, NBB-10228, NBB-10229, NBB-10242, NBB-10251, NBB-10244, NBB-10246, NBB-10247, NBB-10248, NBB-10245, NBB-10249, NBB-10253, NBB-10250, NBB-10252, NBB-10254, NBB-10255, NBB-10256, NBB-10258, NBB-10230, NBB-10231, NBB-10232, NBB-10233, NBB-10260, NBB-10234, NBB-10235, NBB-10236, NBB-10261, NBB-10237, NBB-10263, NBB-10238, NBB-10239, NBB-10262, NBB-10271, NBB-10264, NBB-10266, NBB-10267, NBB-10268, NBB-10265, NBB-10269, NBB-10273, NBB-10270, NBB-10272, NBB-10274, NBB-10275, NBB-10276, NBB-10278, NBB-15220, NBB-15221, NBB-15222, NBB-15223, NBB-15240, NBB-15224, NBB-15225, NBB-15226, NBB-15241, NBB-15227, NBB-15243, NBB-15242, NBB-15251, NBB-15228, NBB-15229, NBB-15246, NBB-15244, NBB-15247, NBB-15248, NBB-15245, NBB-15249, NBB-15253, NBB-15250, NBB-15252, NBB-15254, NBB-15255, NBB-15256, NBB-15258, NBB-15230, NBB-15231, NBB-15232, NBB-15233, NBB-15260, NBB-15234, NBB-15235, NBB-15236, NBB-15261, NBB-15237, NBB-15263, NBB-15242, NBB-15251, NBB-15228, NBB-15229, NBB-15244, NBB-15246, NBB-15267, NBB-15268, NBB-15265, NBB-15269, NBB-15273, NBB-15270, NBB-15272, NBB-15274, NBB-15275, NBB-15276, NBB-15278, NBD-10441, NBD-10442, NBD-10443, NBD-10447, NBD-10449, NBD-10448, NBD-10452, NBD-10453, NBD-10445, NBD-10457, NBD-10456, , NBD-10461, NBD-10462, NBD-10463, NBD-10467, NBD-10469, NBD-10468, NBD-10472, NBD-10473, NBD-10465, NBD-10477, NBD-10476, NBD-15441, NBD-15442, NBD-15443, NBD-15447, NBD-15449, NBD-15448, NBD-15452, NBD-15453, NBD-15445,



Bruce Mahrenholz, Director North American Certification Program

UL LLC


Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20181012-E194432
Report Reference E194432-20181012
Issue Date 2018-OCTOBER-12

Industrial control panel enclosures: Models NBD-15457, NBD-15456, NBD-15461, NBD-15462, NBD-15463, NBD-15467, NBD-15469, NBD-15468, NBD-15472, NBD-15473, NBD-15465, NBD-15477, NBD-15476, NBE-10540, NBE-10527, NBE-10543, NBE-10551, NBE-10544, NBE-10547, NBE-10545, NBE-10549, NBE-10553, NBE-10555, NBE-10558, NBE-10556, NBE-10560, NBE-10537, NBE-10563, NBE-10571, NBE-10564, NBE-10567, NBE-10565, NBE-10569, NBE-10573, NBE-10575, NBE-10578, NBE-10576, NBE-15540, NBE-15527, NBE-15543, NBE-15544, NBE-15547, NBE-15545, NBE-15549, NBE-15553, NBE-15555, NBE-15558, NBE-15556, NBE-15560, NBE-15537, NBE-15563, NBE-15564, NBE-15567, NBE-15565, NBE-15569, NBE-15573, NBE-15575, NBE-15578, NBE-15576, NBF-32102, NBF-32104, NBF-32106, NBF-32108, NBF-32110, NBF-32112, NBF-32114, NBF-32116, NBF-32118, NBF-32120, NBF-32126, NBF-32128, NBF-32130, NBF-32132, NBF-32134, NBF-32136, NBF-32138, NBF-32140, NBF-32142, NBF-32144, NBF-32146, NBC-10352, NBF-32202, NBF-32204, NBF-32206, NBF-32208, NBF-32210, NBF-32212, NBF-32214, NBF-32216, NBF-32218, NBF-32220, NBF-32226, NBF-32228, NBF-32230, NBF-32232, NBF-32234, NBF-32236, NBF-32238, NBF-32240, NBF-32242, NBF-32244, NBF-32246, , NBF-32302, NBF-32304, NBF-32306, NBF-32308, NBF-32310, NBF-32312, NBF-32314, NBF-32316, NBF-32318, NBF-32320, NBF-32326, NBF-32328, NBF-32330, NBF-32332, NBF-32334, NBF-32336, NBF-32338, NBF-32340, NBF-32342, NBF-32344, NBF-32346, NBC-15372, NBF-32402, NBF-32404, NBF-32406, NBF-32408, NBF-32410, NBF-32412, NBF-32414, NBF-32416, NBF-32418, NBF-32420, NBF-32426, NBF-32428, NBF-32430, NBF-32432, NBF-32434, NBF-32436, NBF-32438, NBF-32440, NBF-32442, NBF-32444, NBF-32446, NBG-10641, NBG-10642, NBG-10643, NBG-10647, NBG-10648, NBG-10652, , NBG-10661, NBG-10662, NBG-10663, NBG-10667, NBG-10668, NBG-10672, NBG-15641, NBG-15642, NBG-15643, NBG-15647, NBG-15648, NBG-15652, NBG-15661, NBG-15662, NBG-15663, NBG-15667, NBG-15668, NBG-15672, NBH-10701, NBH-10702, NBH-10703, NBH-10704, NBH-10705, NBH-10706, NBH-10708, NBH-10709, NBH-10710, NBH-10711, NBH-10712, NBH-10713, NBH-10714, NBH-10715, NBH-10717, NBH-10718, NBH-10721, NBH-10722, NBH-10723, NBH-10724, NBH-10725, NBH-10726, NBH-10728, NBH-10729, NBH-10731, NBH-10734, NBH-10735, NBH-10738, NBH-10739, NBH-10740, NBH-10741, NBH-10742, NBH-10743, NBH-10744, NBH-10801, NBH-10802, NBH-10803, NBH-10804,



Bruce Mahrenholz, Director North American Certification Program

UL LLC


Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20181012-E194432
Report Reference E194432-20181012
Issue Date 2018-OCTOBER-12

Industrial control panel enclosures: Models NBH-10805, NBH-10806, NBH-10808, NBH-10809, NBH-10810, NBH-10811, NBH-10812, NBH-10813, NBH-10814, NBH-10815, NBH-10817, NBH-10818, NBH-10821, NBH-10822, NBH-10823, NBH-10824, NBH-10825, NBH-10826, NBH-10828, NBH-10829, NBH-10831, NBH-10834, NBH-10835, NBH-10838, NBH-10839, NBH-10840, NBH-10841, NBH-10842, NBH-10843, NBH-10844, NBH-15701, NBH-15702, NBH-15703, NBH-15704, NBH-15705, NBH-15706, NBH-15708, NBH-15709, NBH-15710, NBH-15711, NBH-15712, NBH-15713, NBH-15714, NBH-15715, NBH-15717, NBH-15718, NBH-15721, NBH-15722, NBH-15723, NBH-15724, NBH-15725, NBH-15726, NBH-15728, NBH-15729, NBH-15731, NBH-15734, NBH-15735, NBH-15738, NBH-15739, NBH-15740, NBH-15741, NBH-15742, NBH-15743, NBH-15744, NBH-15801, NBH-15802, NBH-15803, NBH-15804, NBH-15805, NBH-15806, NBH-15808, NBH-15809, NBH-15810, NBH-15811, NBH-15812, NBH-15813, NBH-15814, NBH-15815, NBH-15817, NBH-15818, NBH-15821, NBH-15822, NBH-15823, NBH-15824, NBH-15825, NBH-15826, NBH-15828, NBH-15829, NBH-15831, NBH-15834, NBH-15835, NBH-15838, NBH-15839, NBH-15840, NBH-15841, NBH-15842, NBH-15843, NBH-15844, 48563, 48563-1, NBF-32422, NBF-32122, NBF-32222, NBF-32322, NBF-32124, NBF-32224, NBF-32324, NBF-32424, , 49352



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

